

System.IO.FileLoadException

While loading assembly Archi-lab_Grimshaw, Version=1.0.0.0, Culture=neutral, PublicKeyToken=null, Dynamo detected that the dependency RevitNodes, Version=2.0.0.4981, Culture=neutral, PublicKeyToken=null was already loaded with an incompatible version. It is likely that another Revit Addin has loaded this assembly, please try uninstalling other Addins, and starting Dynamo again. Dynamo may be unstable in this state.

It is likely one of the following assemblies loaded the incompatible version:

DynamoRevitDS, DynamoRevitDS, DynamoRevitDS, DynamoRevitDS, DynamoRevitDS, DynamoRevitDS, DynamoRevitDS, DynamoRevitDS, DynamoRevitDS, DynamoRevitDS, DynamoRevitDS, RevitServices, RevitServices, RevitServices, DynamoCoreWpf, DynamoCoreWpf, DynamoCoreWpf, DynamoCoreWpf, DynamoCoreWpf, DynamoCoreWpf, DynamoCore, DynamoCore, DynamoCore, DynamoCore, DynamoCore, DynamoCore, DynamoCore, DynamoCore, DynamoApplications, DynamoApplications, ProtoCore, ProtoAssociative, ProtoImperative, Microsoft.GeneratedCode, DynamoUnits, DynamoPackages, DynamoPackages, VMDataBridge, VMDataBridge, DSCoreNodes, DSCoreNodes, DSOOffice, DSOOffice, DSOOffice, DSIronPython, DSIronPython, DynamoConversions, Tessellation, Analysis, Analysis, Analysis, Display, Display, Display, RevitNodes, RevitNodes, RevitNodes, RevitNodes, RevitNodes, RevitNodes, ProtoScript, ProtoScript, ProtoScript, CoreNodeModels, CoreNodeModels, CoreNodeModels, CoreNodeModels, CoreNodeModels, CoreNodeModels, CoreNodeModelsWpf, CoreNodeModelsWpf, CoreNodeModelsWpf, CoreNodeModelsWpf, CoreNodeModelsWpf, CoreNodeModelsWpf, GeometryUI, GeometryUI, GeometryUI, GeometryUI, GeometryUIWpf, GeometryUIWpf, GeometryUIWpf, GeometryUIWpf, Migrations, PythonNodeModels, PythonNodeModels, PythonNodeModels, PythonNodeModelsWpf, PythonNodeModelsWpf, PythonNodeModelsWpf, UnitsUI, UnitsUI, UnitsUI, UnitsUI, UnitsUI, UnitsUI, Watch3DNodeModels, Watch3DNodeModels, Watch3DNodeModels, Watch3DNodeModels, Watch3DNodeModelsWpf, Watch3DNodeModelsWpf, Watch3DNodeModelsWpf, Watch3DNodeModelsWpf, Watch3DNodeModelsWpf, DSRevitNodesUI, DSRevitNodesUI, DSRevitNodesUI, DSRevitNodesUI, DSRevitNodesUI, DSRevitNodesUI, DSRevitNodesUI, DSRevitNodesUI, DSRevitNodesUI, DSRevitNodesUI

While loading assembly archilabUI, Version=1.0.0.0, Culture=neutral, PublicKeyToken=null, Dynamo detected that the dependency RevitNodes, Version=2.0.0.4981, Culture=neutral, PublicKeyToken=null was already loaded with an incompatible version. It is likely that another Revit Addin has loaded this assembly, please try uninstalling other Addins, and starting Dynamo again. Dynamo may be unstable in this state.

It is likely one of the following assemblies loaded the incompatible version:

DynamoRevitDS, DynamoRevitDS, DynamoRevitDS, DynamoRevitDS, DynamoRevitDS, DynamoRevitDS, DynamoRevitDS, DynamoRevitDS, DynamoRevitDS, RevitServices, RevitServices, RevitServices, DynamoCoreWpf, DynamoCoreWpf, DynamoCoreWpf, DynamoCoreWpf, DynamoCoreWpf, DynamoCoreWpf

DynamoCore, DynamoCore, DynamoCore, DynamoCore, DynamoCore, DynamoCore, DynamoCore, DynamoCore, DynamoCore, DynamoApplications, DynamoApplications, ProtoCore, ProtoAssociative, ProtoImperative, Microsoft.GeneratedCode, DynamoUnits, DynamoPackages, DynamoPackages, VMDataBridge, VMDataBridge, DSCoreNodes, DSCoreNodes, DSOOffice, DSOOffice, DSOOffice, DSIronPython, DSIronPython, DynamoConversions, Tessellation, Analysis, Analysis, Analysis, Display, Display, Display, RevitNodes, RevitNodes, RevitNodes, RevitNodes, RevitNodes, RevitNodes, ProtoScript, ProtoScript, ProtoScript, CoreNodeModels, CoreNodeModels, CoreNodeModels, CoreNodeModels, CoreNodeModels, CoreNodeModels, CoreNodeModelsWpf, CoreNodeModelsWpf, CoreNodeModelsWpf, CoreNodeModelsWpf, CoreNodeModelsWpf, CoreNodeModelsWpf, GeometryUI, GeometryUI, GeometryUI, GeometryUI, GeometryUIWpf, GeometryUIWpf, GeometryUIWpf, GeometryUIWpf, Migrations, PythonNodeModels, PythonNodeModels, PythonNodeModels, PythonNodeModels, PythonNodeModelsWpf, PythonNodeModelsWpf, PythonNodeModelsWpf, UnitsUI, UnitsUI, UnitsUI, UnitsUI, UnitsUI, UnitsUI, Watch3DNodeModels, Watch3DNodeModels, Watch3DNodeModels, Watch3DNodeModels, Watch3DNodeModelsWpf, Watch3DNodeModelsWpf, Watch3DNodeModelsWpf, Watch3DNodeModelsWpf, Watch3DNodeModelsWpf, Watch3DNodeModelsWpf, DSRevitNodesUI, DSRevitNodesUI, DSRevitNodesUI, DSRevitNodesUI, DSRevitNodesUI, DSRevitNodesUI, DSRevitNodesUI, DSRevitNodesUI, DSRevitNodesUI, DSRevitNodesUI, DSRevitNodesUI

While loading assembly EO.WebBrowser, Version=16.2.9.0, Culture=neutral, PublicKeyToken=e92353a6bf73fffc, Dynamo detected that the dependency EO.WebBrowser, Version=16.2.9.0, Culture=neutral, PublicKeyToken=e92353a6bf73fffc was already loaded with an incompatible version. It is likely that another Revit Addin has loaded this assembly, please try uninstalling other Addins, and starting Dynamo again. Dynamo may be unstable in this state.

It is likely one of the following assemblies loaded the incompatible version:

EnergyAnalysis, EO.WebBrowser, EO.WebBrowser

While loading assembly EO.WebBrowser.Wpf, Version=16.2.9.0, Culture=neutral, PublicKeyToken=e92353a6bf73fffc, Dynamo detected that the dependency EO.WebBrowser, Version=16.2.9.0, Culture=neutral, PublicKeyToken=e92353a6bf73fffc was already loaded with an incompatible version. It is likely that another Revit Addin has loaded this assembly, please try uninstalling other Addins, and starting Dynamo again. Dynamo may be unstable in this state.

It is likely one of the following assemblies loaded the incompatible version:

EnergyAnalysis, EO.WebBrowser, EO.WebBrowser

While loading assembly Mandrill_License, Version=1.0.0.0, Culture=neutral, PublicKeyToken=null, Dynamo detected that the dependency EO.WebBrowser, Version=16.2.50.0, Culture=neutral, PublicKeyToken=e92353a6bf73ffc was already loaded with an incompatible version. It is likely that another Revit Addin has loaded this assembly, please try uninstalling other Addins, and starting Dynamo again. Dynamo may be unstable in this state.

It is likely one of the following assemblies loaded the incompatible version:

EnergyAnalysis, EO.WebBrowser, EO.WebBrowser

While loading assembly Mandrill_UI, Version=1.0.0.0, Culture=neutral, PublicKeyToken=null, Dynamo detected that the dependency EO.WebBrowser, Version=16.2.9.0, Culture=neutral, PublicKeyToken=e92353a6bf73ffc was already loaded with an incompatible version. It is likely that another Revit Addin has loaded this assembly, please try uninstalling other Addins, and starting Dynamo again. Dynamo may be unstable in this state.

It is likely one of the following assemblies loaded the incompatible version:

EnergyAnalysis, EO.WebBrowser, EO.WebBrowser